







8 7 6 5 4 3 2 1

F


E

D

C

B

A



PART NAME

1 Microswitches Support - 2mm
Thickness - Quantity 8

SCREWS LIST

2 M3 x 6 + M3 Nuts
Quantity: 12

3 M3 x 10 Screw + M3 Nuts
Quantity: 16

4 M3 x 8 + M3 Nuts
Quantity: 4

F



E

D


C

B

A



8 7 6 5 4 3 2 1



- 1 X Mobile Part
- 2 M8 x 170 No Head Screw
- 3 Drill Bit Stop Collar (Inner Diameter: Ø8mm)
2 x M3x5 No Head Screws
- 4 Compression Spring (20mm Height)
- 5 19x6x6 Ball Bearings
- 6 Part Name: Ball Bearing Support - 2mm Thickness
- 7 M6 x 16 Screws + M6 Lock Nuts
Quantity: 2 - Note: Ball Bearing Fixing
- 8 M8 Female Rodend (SI8TK M8 Right)
- 9 M5 Nut + M5 Lock Nut - Quantity: 4
Note: Traction Spring Fixing
- 10 M5 x 16 Screws + M5 Nuts + M5 Lock Nuts
Quantity: 4 - Note: Traction Spring Fixing
- 11 M8 x 120 Half Thread Bolt + M8 Lock Nut
- 12 Traction Springs (back to neutral gear)
- 13 Part Name: Axis Washer - 5mm Thickness - Quantity 4
- 14 Part Name: Axis Washer - 3mm Thickness - Quantity 1